

FIGURE 1C

FIGURE 10






Figure 3





600-1	600-	2 600-3	600-	4 محم 4	-5 60 (0-6 / 6	60 -7
PRODUCT CODE	OP	OFFSET					
			(ioin			<u> </u>	,

FIGURE LA

OPTIONS (OFFSET) TABLE

- A. COMMUNICATIONS OPTIONS
 - 1. RS-232
 - 2. BAUD RATE
 - 3. RF LINK
 - 4. ETHERNET
- B. CODE OPTIONS
- 1. DISABLE 1D
 - 2. DISABLE 2D
 - 3. DISABLE INDIV.
 - 4. MIN-MAX LENGTH
- 5. MULTIPLE SYMBOLS ENABLED
- C. SCANNING-DECODING OPTIONS
 - 1. ONE SHOT
 - 2. REPEAT UNTIL DONE
 - 3. REPEAT UNTIL STOPPED
 - 4. SCAN ON DEMAND
 - 5. SKIP SCAN
 - 6. DECODE ON DEMAND
- D. OPERATING OPTIONS
 - 1. BEEPER VOLUME
 - 2. Alming LED on/off
 - 3. AURAL FEEDBACK
- E. TRANSMIT OPTIONS
 - 1. SEND CHECK CHAR'S
 - 2. SEND CHECKSUM
 - 3. DATA EDIT OPTIONS

F READER MODE OPTIONS

- 1. Automatic
- 2. SEMI-ANDMOTIC
- 3 Bar adi Scan
- 4. OCK
- 5. Signature
- 6. Color Imaging

FIGURE 6B

OP CODE TABLE

- A. OP CODE "O"-VECTOR PROC.

 1. OUTPUT VERSION
 - OF SOFTWARE
 - 2. OUTPUT CONTENTS OF PARAMETER TABLE
 - 3. DISPLAY ENABLED CODES
 - 4. PRINT PARAMETER TABLE AS BAR CODE SYMBOL
- B. OP CODE "1" CLEAR
- C. OP CODE "2" SET
- D. OP CODE "3" TOGGLE
- E. OP CODE "4" ADD
- F. OP CODE "5" DEFAULT
- G. OP CODE "6" LOAD
- H. OP CODE "7" RESERVED

FIGURE 6C





FIGURE 7






FIGURE 9




FIGURE 10




FIGURE 11




FIGURE 12




FIGURE 13




FIGURE 14




FIGURE 15

							/ · · · / · · · · / · · · · · · · · · ·	[00
SCAPNER ADDRESS	SEQUENCE PURCEER	LERKTHE	image	TTPE	, MAGE	DATA	ERROR CHECK	Ì

FIGURE 11A





FIGURE 16B






FIGURE 18